

## 9 Type designation

	<b>H</b>	<b>XXX - X</b>
Series		
Upper force limit		
100, 200, 300 N		
Version of force sensors		
1 - fitting thread M10x1;		
2 - fitting thread M20x1		

### Order example of force sensor

Force sensor of H series, intended for force conversion from 0 to 100 N, with fitting thread M10x1:

Force sensor H 100-1.

Note: if wished, the wire length (standard 80 mm) can be changed, in this case the required length should be added to the wire code L, for example:

Force sensor H 100-1-L130.

## 10 Marking

Marking on the sensor body must contain following information: designation of the sensor and order number.

*Microtensor*

Force sensors H Series